

CONSTRUCTION UPDATE | 09.10.2021

CONSTRUCTION UPDATE: CURRENT (09/10)

- Lower Level
 - Wall framing and sheathing activity are ongoing.
 - Ceiling framing and grid activity are ongoing.
 - Overhead and in wall MEP activity are ongoing.
 - Prime and paint activity are ongoing.
 - Tile wall and flooring activity are ongoing.
- Plaza Level
 - Wall framing and sheathing activity are ongoing.
 - CMU activity is ongoing.
 - Overhead and in wall MEP activity is ongoing.
 - Prime paint activity is ongoing.
 - Tile wall and flooring activity are ongoing.
 - Service drive overbuild slab activity is ongoing.
- 1st Floor
 - Wall framing and sheathing activity are ongoing.
 - Overhead and inwall MEP activity are ongoing.
 - Prime paint activity is ongoing.
 - Tile wall and flooring activity is ongoing.
- 2nd Floor
 - Wall framing and sheathing activity are ongoing.
 - Curtain wall and glazing activity are ongoing.
 - Overhead and in wall MEP activity is ongoing.
 - Prime paint activity is ongoing.
 - Tile flooring activity is ongoing.
- 3rd Floor
 - Wall framing and sheathing activity is ongoing.
 - Overhead and in wall MEP activity is ongoing.
 - Prime paint activity is ongoing.
- 4th Floor
 - Wall framing and sheathing activity is ongoing.
 - Overhead MEP activity is ongoing.
- 5th Floor
 - Wall framing activity is ongoing.
 - Overhead MEP activity is ongoing.
- 6th Floor
 - Wall framing activity is ongoing.
 - Overhead MEP activity is ongoing.
- 7th Floor
 - Overhead MEP activity is ongoing.
- 8th Floor
 - Exterior wall framing and sheathing activity are ongoing.
 - Exterior waterproofing is ongoing.
 - Curtain wall activity is ongoing.
 - Overhead MEP activity has started.
- Penthouse Level
 - Gutter installation at mansard is ongoing.
 - Penthouse Mezzanine wall framing, and sheathing is ongoing.

- Elevator equipment installation is ongoing.
- Stone sill activity on the west, south, east and north elevation are ongoing.
- EIFS activity on the west and south elevation are ongoing.
- Site hardscape activity is ongoing.
- Stair 2 intumescent fireproofing is ongoing.

CONSTRUCTION ACTIVITIES: PREVIOUS WEEK (9/03)

- Lower Level
 - Wall framing and sheathing activity were ongoing.
 - Ceiling framing and grid activity were ongoing.
 - Overhead and in wall MEP activity were ongoing.
 - Prime and paint activity were ongoing.
 - Tile wall and flooring activity were ongoing.
- Plaza Level
 - Wall framing and sheathing activity were ongoing.
 - CMU activity was ongoing.
 - Overhead and in wall MEP activity was ongoing.
 - Prime paint activity was ongoing.
 - Tile wall and flooring activity were ongoing.
 - Service drive overbuild slab activity was ongoing.
- 1st Floor
 - Wall framing and sheathing activity were ongoing.
 - Overhead and inwall MEP activity were ongoing.
 - Prime paint activity was ongoing.
 - Tile flooring activity was ongoing.
- 2nd Floor
 - Wall framing and sheathing activity were ongoing.
 - Curtain wall and glazing activity were ongoing.
 - Overhead and in wall MEP activity was ongoing.
 - Prime paint activity was ongoing.
 - Tile flooring activity was ongoing.
- 3rd Floor
 - Wall framing and sheathing activity was ongoing.
 - Overhead and in wall MEP activity was ongoing.
 - Prime paint activity was ongoing.
- 4th Floor
 - Wall framing and sheathing activity was ongoing.
 - Overhead MEP activity was ongoing.
- 5th Floor
 - Wall framing activity was ongoing.
 - Overhead MEP activity was ongoing.
- 6th Floor
 - Wall framing activity was ongoing.
 - Overhead MEP activity was ongoing.
- 7th Floor
 - Overhead MEP activity was ongoing.
- 8th Floor
 - Exterior wall framing and sheathing activity were ongoing.
 - Exterior waterproofing was ongoing.

- Curtain wall activity was ongoing.
 - Overhead MEP activity was started.
- Penthouse Level
 - Gutter installation at mansard was ongoing.
 - Penthouse Mezzanine wall framing, and sheathing was ongoing.
- Elevator equipment installation was ongoing.
- Stone sill activity on the west, south and east elevation were ongoing.
- EIFS activity on the west and south elevation were ongoing.
- Site hardscape activity was ongoing.

CONSTRUCTION ACTIVITIES: UPCOMING WEEK(S)

- Roofing activity.
- MCM exterior panels.
- Light fixture installation.
- Flooring and wall tile activity.
- Vanity countertops
- Millwork

PROGRESS PHOTOS



