

## CONSTRUCTION UPDATE | 05.28.2021

---

### CONSTRUCTION UPDATE: CURRENT (05/28)

- Lower Level
  - Foundation wall waterproofing activity is ongoing.
  - Wall framing and sheathing activity is ongoing.
  - Overhead and in wall MEP activity is ongoing.
- Plaza Level
  - Wall framing and sheathing activity is ongoing.
  - CMU activity is ongoing.
  - Overhead and in wall MEP activity is ongoing.
- 1<sup>st</sup> Floor
  - Wall framing and sheathing activity is ongoing.
  - Exterior soffit framing activity is ongoing.
  - Exterior skin waterproofing is ongoing.
  - CMU activity is ongoing.
  - Overhead and inwall MEP activity is ongoing.
- 2<sup>nd</sup> Floor
  - Wall framing and sheathing activity is ongoing.
  - Exterior soffit framing activity was completed.
  - Exterior skin waterproofing is ongoing.
  - CMU activity is ongoing.
  - Curtain wall and glazing activity is ongoing.
  - Overhead and in wall MEP activity is ongoing.
  - Spray fireproofing activity was completed.
- 3<sup>rd</sup> Floor
  - Wall framing activity is ongoing.
  - Exterior wall framing and sheathing activity is ongoing.
  - Exterior skin waterproofing is ongoing.
  - Curtain wall and glazing activity is ongoing.
  - Overhead MEP activity is ongoing.
- 4<sup>th</sup> Floor
  - Exterior wall framing and sheathing activity is ongoing.
  - Exterior skin waterproofing is ongoing.
  - Curtain wall and glazing activity is ongoing.
- 5<sup>th</sup> Floor
  - Exterior wall framing and sheathing activity is ongoing.
  - Exterior skin waterproofing is ongoing.
  - Curtain wall and glazing activity is ongoing.
- 8<sup>th</sup> Floor
  - Structural steel activity is ongoing.
- HW/CW line tie in activity is ongoing.
- Stair 1 and Stair 4 riser installation is ongoing.

#### CONSTRUCTION ACTIVITIES: PREVIOUS WEEK (5/21)

- Lower Level
  - Wall framing and sheathing activity was ongoing.
  - CMU activity was completed.
  - Overhead and in wall MEP activity was ongoing.
  - Structural steel installation was completed.
- Plaza Level
  - Wall framing and sheathing activity was ongoing.
  - CMU activity was ongoing.
  - Overhead and in wall MEP activity was ongoing.
- 1<sup>st</sup> Floor
  - Wall framing and sheathing activity was ongoing.
  - Exterior soffit framing activity was ongoing.
  - Exterior skin waterproofing was ongoing.
  - CMU activity was ongoing.
  - Overhead and inwall MEP activity was ongoing.
  - Spray fireproofing activity was completed.
- 2<sup>nd</sup> Floor
  - Wall framing and sheathing activity was ongoing.
  - Exterior soffit framing activity was ongoing.
  - Exterior skin waterproofing was ongoing.
  - CMU activity was ongoing.
  - Curtain wall and glazing activity was ongoing.
  - Overhead and in wall MEP activity was ongoing.
  - Spray fireproofing activity was ongoing.
- 3<sup>rd</sup> Floor
  - Wall framing activity was ongoing.
  - Exterior wall framing and sheathing activity was ongoing.
  - Exterior skin waterproofing was ongoing.
  - Curtain wall and glazing activity was ongoing.
  - Overhead MEP activity was ongoing.
- 4<sup>th</sup> Floor
  - Exterior wall framing and sheathing activity was ongoing.
  - Exterior skin waterproofing was ongoing.
  - Curtain wall and glazing activity was ongoing.
- 5<sup>th</sup> Floor
  - Exterior wall framing and sheathing activity was ongoing.
  - Exterior skin waterproofing was ongoing.
  - Curtain wall and glazing activity was ongoing.
- 8<sup>th</sup> Floor
  - Structural steel activity was ongoing.
- HW/CW line tie in activity was ongoing.
- Stair 1 and Stair 4 riser installation was ongoing.



**CONSTRUCTION ACTIVITIES: UPCOMING WEEK(S)**

- Slab on metal deck.
- CMU activity.
- Fireproofing at structural steel activity.
- Curtain wall activity.
- Stone activity.

PROGRESS PHOTOS



