

## CONSTRUCTION UPDATE | 09.03.2021

---

### CONSTRUCTION UPDATE: CURRENT (09/03)

- Lower Level
  - Wall framing and sheathing activity are ongoing.
  - Ceiling framing and grid activity are ongoing.
  - Overhead and in wall MEP activity are ongoing.
  - Prime and paint activity are ongoing.
  - Tile wall and flooring activity are ongoing.
- Plaza Level
  - Wall framing and sheathing activity are ongoing.
  - CMU activity is ongoing.
  - Overhead and in wall MEP activity is ongoing.
  - Prime paint activity is ongoing.
  - Tile wall and flooring activity are ongoing.
  - Service drive overbuild slab activity is ongoing.
- 1<sup>st</sup> Floor
  - Wall framing and sheathing activity are ongoing.
  - Overhead and inwall MEP activity are ongoing.
  - Prime paint activity is ongoing.
  - Tile flooring activity is ongoing.
- 2<sup>nd</sup> Floor
  - Wall framing and sheathing activity are ongoing.
  - Curtain wall and glazing activity are ongoing.
  - Overhead and in wall MEP activity is ongoing.
  - Prime paint activity is ongoing.
  - Tile flooring activity is ongoing.
- 3<sup>rd</sup> Floor
  - Wall framing and sheathing activity is ongoing.
  - Overhead and in wall MEP activity is ongoing.
  - Prime paint activity is ongoing.
- 4<sup>th</sup> Floor
  - Wall framing and sheathing activity is ongoing.
  - Overhead MEP activity is ongoing.
- 5<sup>th</sup> Floor
  - Wall framing activity is ongoing.
  - Overhead MEP activity is ongoing.
- 6<sup>th</sup> Floor
  - Wall framing activity is ongoing.
  - Overhead MEP activity is ongoing.
- 7<sup>th</sup> Floor
  - Overhead MEP activity has ongoing.
- 8<sup>th</sup> Floor
  - Exterior wall framing and sheathing activity are ongoing.
  - Exterior waterproofing is ongoing.
  - Curtain wall activity is ongoing.
  - Overhead MEP activity has started.
- Penthouse Level
  - Gutter installation at mansard is ongoing.
  - Penthouse Mezzanine wall framing, and sheathing is ongoing.

- Elevator equipment installation is ongoing.
- Stone sill activity on the west, south and east elevation are ongoing.
- EIFS activity on the west and south elevation are ongoing.
- Site hardscape activity is ongoing.

#### CONSTRUCTION ACTIVITIES: PREVIOUS WEEK (8/27)

- Lower Level
  - Wall framing and sheathing activity were ongoing.
  - Ceiling framing and grid activity were ongoing.
  - Overhead and in wall MEP activity were ongoing.
  - Prime and paint activity were ongoing.
  - Tile flooring activity was ongoing.
- Plaza Level
  - Wall framing and sheathing activity were ongoing.
  - CMU activity was ongoing.
  - Overhead and in wall MEP activity were ongoing.
  - Prime paint activity was ongoing.
  - Tile flooring activity was ongoing.
  - Service drive overbuild slab activity was ongoing.
- 1<sup>st</sup> Floor
  - Wall framing and sheathing activity were ongoing.
  - Overhead and inwall MEP activity were ongoing.
  - Prime paint activity was ongoing.
  - Tile flooring activity was ongoing.
- 2<sup>nd</sup> Floor
  - Wall framing and sheathing activity were ongoing.
  - Curtain wall and glazing activity were ongoing.
  - Overhead and in wall MEP activity were ongoing.
  - Prime paint activity was ongoing.
  - Tile flooring activity was ongoing.
- 3<sup>rd</sup> Floor
  - Wall framing and sheathing activity was ongoing.
  - Overhead and in wall MEP activity was ongoing.
  - Prime paint activity was ongoing.
- 4<sup>th</sup> Floor
  - Wall framing and sheathing activity was ongoing.
  - Overhead MEP activity was ongoing.
- 5<sup>th</sup> Floor
  - Wall framing activity was ongoing.
  - Overhead MEP activity was ongoing.
- 6<sup>th</sup> Floor
  - Overhead MEP activity was ongoing.
- 7<sup>th</sup> Floor
  - Overhead MEP activity was ongoing.
- 8<sup>th</sup> Floor
  - Exterior wall framing and sheathing activity were ongoing.
  - Exterior waterproofing was ongoing.
  - Curtain wall activity was ongoing.
  - Overhead MEP activity was started.

- Penthouse Level
  - Gutter installation at mansard was ongoing.
  - Penthouse Mezzanine wall framing, and sheathing was ongoing.
- Elevator equipment installation was ongoing.
- Stone sill activity on the west, south and east elevation were ongoing.
- EIFS activity on the west and south elevation were ongoing.
- Site hardscape activity was ongoing.

**CONSTRUCTION ACTIVITIES: UPCOMING WEEK(S)**

- Roofing activity.
- MCM exterior panels.
- Light fixture installation.
- Flooring and wall tile activity.
- Vanity countertops
- Millwork

PROGRESS PHOTOS



